

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 33

Township: 7 North


Range: 1 East

Corner ID: Polk K-25

Monument Description & Remarks: 3" Brass Disk stamped, "1/4 S.33 T7N, S.4 T6N, 1973 SO143". Survey Sign 5ft above ground at pt. B

References On File: Andrew J. Sobiech certified land corner restoration, Monument Record (1973), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 41



A - 3" Brass Disk

B - S 89° W 3.92' to Survey
Sign on 4" Sugar Maple

C - N 86° E 16.60' to MAG
nail in 14" Shagbark Hickory

D - S 24° E 21.45' to MAG
nail on 6" Shagbark Hickory

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 8th day of September, 2008.

Administered by the Monroe County Surveyor Review Board

Date: 10/7/2008



[K-25]

HO-5880-14 (5/1/64)

H. C. MILLER CO., MILWAUKEE 447802

CERTIFIED LAND CORNER RESTORATION

State of Indiana }
County of Monroe } ss.

I, Andrew J. Sobiech, do hereby certify that on the 24th day of May, 1973, I found evidence of the South Quarter corner of Section 33 Township 7N, Range 1E, Second Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was a wood post set in 1811.	Filed in Book 1, page 290.
Original witness trees:	A sandstone was set by county surveyor, James Spencer with following witnesses:
Chestnut Oak	Chestnut Oak
24"	36"
76° E	N 30°30'W
19 lks	6 lks
Dogwood	Hickory
6"	15"
27° W	S 08° W
24 lks	74 lks

See also:
Book 2, page 324

Description of corner evidence found:

Found sandstone 8" x 4" x 1 ft. long planted flush with ground, marked with a +. A fence from the north and west intersects at stone. The location of the stone is also the corner of fields open to the south and east, wooded to the NW.

Description of monument and accessories I established to perpetuate the original location of this corner:

I replaced the stone with a 2" I.D. by 3 ft. long concrete filled galvanized iron pipe capped with a 3 inch diameter brass tablet stamped to identify the corner. I established the following witnesses:

Shagbark Hickory	Black Oak	Cottonwood	Sign Post
6"	24"	7"	4'x4'
N 80° E	N 05° W	S 60° E	S 62° E
16.8 ft.	20.3 ft.	18.2 ft.	3.6 ft.

T7N R1E

Field Assistant
Resident witness Henry Deaton U.S.F.S.

Dated at Brownstown Indiana, this 24 day of May 1973.

Index No. 2-11
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E Mer. N.F. Hossier County Monroe State Indiana
5 1/4 Corner common to sections 33 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1811
Original monument wood post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species chestnut
Diameter 30"
Bearing N76°E
Distance 29 1/2

Subsequent Corner Restoration

Year surveyed 1855 By James Spencer
Where filed or recorded Monroe Co Survey Bk. Pg. 290
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species chestnut
Diameter 36"
Bearing N30°W
Distance 6 1/2

Original Evidence Found

Year of search 1972 By H. Doston B. Ayer
Monument found No

Original Bearing Trees Found


Species _____
Diameter _____
Bearing None
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1972 By H. Doston B.A.

Bearing Trees, Reference Objects

None



Sketch

O Corner ☒ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Road lies 207 ft. east of stone
A fence from North and West intersect at the stone. A sandstone flush w/ground, with + on top.

Perpetuation Record

Monument and accessories established. Include brief description of area.

At time of search:

1. Did you have the record description?
Yes ☒ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Maps, photos

3. Man hours spent in search 1 1/2 hrs

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature H. Doston

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____